PROJECT DESCRIPTION

EQUIPMENT LIST

A. Equipment to be supplied by the Administration

Ī.	General		Item No.	Quantity	Units	Speci	ficat Secti	
	This project involves the modificatraffic signal with interconnect (Branch Ave) at Colebrook Drive in Maryland. MD 5 is assumed to run	at the intersection of MD 5 D Prince George's County.		4	EA	814		12 in, 1 way 3 section (R,Y,G) polycarbonate signal head — span mount.
II.	Intersection Operation			Aprocess	EA	814		12 in. 1 way 5 section (R.Y.G.YA.GA)
	No change to the existing signal a intersection.	operation is required at this	\$					polycarbonate signal head - span mount.
111.	Special Notes			2	EA	814		Combination 8 in./12 in. 1 way 5 section (8 in. R,Y,G /12 in. YA,GA) polycarbonate signal head
	1.) Maintenance of traffic will to utilizing the following stand control: 104.00-104.00-30, 104.40-02, 104.41-02, 104.44-	lard plates for traffic)4.32-02,104.33-02, 104.38-02, 104.39-0	02,	2	EA	814		- span mount. 12 in. one-way 2 section pedestrian signal
	2.) The following are SHA Distric	ct 3 Contact persons:		2	EA	814		head pole mount 12 in. two-way 2
	Mr. Richard L. Daff, Sr. Chief, Traffic Operations Division (410) 787–7630	Mr. Charles Watkins District Engineer (301) 513-7311		<i>t_</i>	LA	014		section pedestrian signal head - pedestal mount
	Mr. Majib Shakib	Mr. Randy Brown		2	EA	817		Pedestrian pushbutton and R10-3c sign
	Asst. District Engineer – Traffic (301) 513–7358	Asst. District Engineer – Maintenance (301) 513-7304		27	SF	813		Sheet aluminum signs consisting of:
	Mr. Augustine Rebish District Engineer- Utility					2 E	ĒΑ	R10-12, (36 in. x 42 in.) span wire mount.
	(301) 513-7350					1 E		D3-2 (var x 16 in.) Dual span wire mount
						1 E		R10-11b (30 in. x 30 in.) span wire mount

EQUIPMENT LIST

B. Equipment to be furnished and/or installed by the Contractor.

D. Equip	70 50	7 10111131160		
Item No.	Quantity	Units	Specifico Sect	ation tion Description
	2	CY	205	Test pit excavation
	740	LF	555	12 in, white reflective theroplastic pavement marking
	170	LF	555	24 in. white reflective thermoplastic pavement marking
	5	CY	801	Furnish and install concrete for signal foundation.
	2	EA	804	Furnish and install ground rod — 3/4 in. diameter x 10 ft.
	200	LF	805	Furnish and install 3 in. schedule 80 rigid PVC conduit – slotted.
	60	LF	805	Furnish and install 3 in. schedule 80 rigid PVC conduit – trenched.
	400	, LF	805	Furnish and install 2 in. schedule 80 rigid PVC conduit – Trenched.
	10	LF	805	Furnish and install 1 in. liquid tight flexible non-metallic conduit for detector wire sleeve.
	30	LF	805	Furnish and install 1 in. electrical conduit – galvanized sleeve
	125	LF	810	Furnish and install No. 6 AWG standard bare copper ground wire.
	410	LF	810	Furnish and install electrical cable – 2 conductor (Aluminum shielded).
	2370	LF	810	Furnish and install electrical cable – 7 conductor (No. 14 AWG).
	1920	LF	810	Furnish and install loop wire encased in flexible tubing (No. 14 AWG).
	4	EA	811	Furnish and install electrical handhole.
	27	SF	813	Install overhead sign - for signals.
	11	EA	814	Install signal head — any type.
	450	LF	815	Furnish and install saw cut for signal.
	1	EA	818	Furnish and install 12 in. X 32 ft. steel strain pole with four - 2 1/4 in. x 96 in. anchor bolts
	290	LF	819	Furnish and install 3/8 in. steel span wire.
	290	LF	819	Furnish and install 1/4 in. tether wire.
	LS	LS	×××	Removal and disposal of existing materials.
	1	EA	818	Furnish and install 10 ft. breakaway pedestal pol
	1	EA	×××	Furnish and install breakaway based support system.
	2 .	EA	×××	Install pushbutton and sign.
	2	EA	818	Re-ring existing span wire

	REVISIONS	APPROVALS	MARYLAND DOT - STATE HIGHWAY ADMINISTRATION Office of Traffic & Safety						
		ASST. DIVISION CHIEF, TEDD							
			TRAFFIC ENGINEERING DESIGN DIVISION						
		ASST. DISTRICT ENGINEER, TRAFFIC	MD 5 (BRANCH AVE) @ COLEBROOK DRIVE GENERAL INFORMATION SHEET 2 OF 2						
		CHIEF, TRAFFIC ENGINEERING DESIGN DIVISION	LOGMILE #:16000514.30 DATE / /						
			DRAWN BY: DCI F.A.P. NO. P-388-000-385 PLAN SHEET NO. SHEET NO.						
ONSULTING ENGINEERS COLUMBIA, MARYLAND	- The state of the	DIRECTOR, OFFICE OF TRAFFIC & SAFETY	SCALE: 8-31-98 1"=20' COUNTY PRINCE GEORGE'S TS-1066 OF						